

Attachment #4
Box 3

Case 1:04-cv-10414-RCL

Document 29-6

Filed 02/03/2006

Page 1 of 13

Invoice

Wholesale Electronics
9101 W. SAHARA #105-D24
Las Vegas, NV 89117
702-739-5990

DATE	INVOICE #
2/28/2001	13265

BILL TO

JOE AMARO
333 COHANNET ST.
TAUNTON, MA 02780

SHIP TO

JOE AMARO
333 COHANNET ST.
TAUNTON, MA 02780
508-880-0617
508-942-4398 CELL

P.O. NUMBER	TERMS	REP	SHIP	VIA	F.O.B.	PROJECT
02780	VISA	MC	2/28/2001	UPS 1 SAVER		
QUANTITY	ITEM CODE	DESCRIPTION			PRICE EACH	AMOUNT
11	VM4	VM4040 UNIVERSAL			70.00	770.00
1	VM4	VM4- PLATINUM UNIVERSAL			70.00	70.00
		SUBTOTAL				840.00
	F	FREIGHT			124.00	124.00
		5490-9911-2830-7978 1/02				
<div>9101 WEST SAHARA #105-D24 LAS VEGAS, NV 89117 702-739-5990</div> <div>02/28/01 15:52:03 REF#: 02010 ECH: 125 STR#: 0001 TERM: 0001 S-A-L-E-S D-T-R-I-B-U-T-E</div> <div>REF: 02010 ECH: 125 CD TYPE: ME PR TYPE: MP INV #: 13265</div> <div>TOTAL: \$964.00 COST: \$400.00 EXP: 01/01/02 AUS: 5490-9911-2830-7978</div> <div>CARRIER: ACKNOWLEDGEMENT RECEIPT OF GOODS AND/OR SERVICES TO THE CARRIER OF THE TOTAL SHOWN HEREON AND AGREES TO PERFORM THE OBLIGATIONS OF THE MEMBER'S AGREEMENT WITH THE ISSUER</div> <div>TOP COPY-MERCHANT BOTTOM COPY-CUSTOMER</div>						
Thank you for your business.					Total	\$964.00

All products carry a 30 day money back guarantee and a 1 year parts and labor warranty. If within 30 days of purchase you are not satisfied, you may return your order for refund or exchange (less S&H). No refunds after 30 days. All returned products must have prior return authorization (RA) approval and must be received within 14 days of obtaining the RA. All returned products must be complete, in un-tampered original condition, including all original boxes, components, manuals, paperwork, etc. and must include invoice showing the RA number assigned for the return. All merchandise ordered in error, returned without authorization, or returned incomplete, will be assessed a 25% restocking fee. All shipping, handling, and insurance fees are at customers expense. All returned merchandise must show a legible RA number on the shipping label. For technical support call

EVIDENCE # 3A PACKAGE # 3

AT&T BROADBAND
CONVERTER TEST FORM

Date	3-9-01	Corp. #	I-COMS
Account #	43747-04	Converter #	010200138
Name:	Joe Amaro / Dimas Amaro	Converter Type:	View Master 4040
Address:	333 Cohannet Street	Received From:	UPS pursuant to warrant on 3/9/01
City:	Taunton	State/Zip	Ma. 02780
SSN#:		Generated From:	

Currently Receiving Unauthorized Service:

All Pay Channels	<u>Yes</u>	All PPV Movies	<u>Yes</u>
------------------	------------	----------------	------------

Pre 4 Point Test

CODES RECEIVED

OTHER NOTABLE FEATURES

OUTSIDE CONVERTER APPEARANCE

<u>P</u>	Security Tabs Missing
<u>I</u>	Outside Screws Missing
<u>R</u>	Converter Damaged
<u>A</u>	Marks Around Outside Screw
<u>T</u>	Wires Cut
<u>E</u>	Tampered Codes

INSIDE CONVERTER APPEARANCE

<u>U</u>	ADP Module Forced Open
<u>N</u>	ADP Module Cover Missing
<u>I</u>	Scratches/Marks on Key Chips
<u>I</u>	Jumper Wires Still In Place
<u>T</u>	Scratches/Marks on Legs of Key Chips
	Missing Prom #

4 Point Test

	Testing Point	Codes/Comments	Pass/Fail
1.	Check Video on converter (e.g. channel 5 or PPV barker on all channels.)	<u>P</u>	<u>U</u>
2.	Converter has 210 code or higher	<u>I</u>	<u>N</u>
3.	Converter has H-1 or H6 code, or tunes 01-99 or 01-128 consecutively.	<u>R</u>	<u>I</u>
4.	Converter does not initialize (i.e. an addressable hit)	<u>ATE</u>	<u>T</u>

Of the 4 points, how many points does it have?

Test Completed By:

Special Project Auditor Paul Marmelo

Date Completed On:

June 25, 2001

Comments:

Confirmed Pirate Device (decoder)

FOR OFFICE USE ONLY:

CONVERTER INSTALLED

BY

CONVERTER REMOVED

3/9/01

BY

TAUNTON POLICE DEPARTMENT

ACCOUNT HISTORY SUMMARY

EVIDENCE # 3B PACKAGE # 3

AT&T BROADBAND
CONVERTER TEST FORM

Date	3-9-01	Corp. #	I-COMS
Account #	43747-04	Converter #	010200552
Name:	Joe Amaro / Dimas Amaro	Converter Type:	View Master 4040
Address:	333 Cohannet Street	Received From:	UPS pursuant to warrant on 3/9/01
City:	Taunton	State/Zip	Ma. 02780
SSN#:		Generated From:	

Currently Receiving Unauthorized Service:

All Pay Channels	<u>Yes</u>	All PPV Movies	<u>Yes</u>
------------------	------------	----------------	------------

Pre 4 Point Test

CODES RECEIVED

OTHER NOTABLE FEATURES

OUTSIDE CONVERTER APPEARANCE

<u>P</u>	Security Tabs Missing
<u>I</u>	Outside Screws Missing
<u>R</u>	Converter Damaged
<u>A</u>	Marks Around Outside Screw
<u>T</u>	Wires Cut
<u>E</u>	Tampered Codes

INSIDE CONVERTER APPEARANCE

<u>U</u>	ADP Module Forced Open
<u>U</u>	ADP Module Cover Missing
<u>N</u>	Scratches/Marks on Key Chips
<u>I</u>	Jumper Wires Still In Place
<u>T</u>	Scratches/Marks on Legs of Key Chips
	Missing Prom #

4 Point Test

	Testing Point	Codes/Comments	Pass/Fail
1.	Check Video on converter (e.g. channel 5 or PPV barker on all channels.)	<u>P</u>	<u>U</u>
2.	Converter has 210 code or higher	<u>I</u>	<u>N</u>
3.	Converter has H-1 or H6 code, or tunes 01-99 or 01-128 consecutively.	<u>R</u>	<u>I</u>
4.	Converter does not initialize (i.e. an addressable hit)	<u>ATE</u>	<u>T</u>

Of the 4 points, how many points does it have?

Test Completed By:

Special Project Auditor Paul Marmelo

Date Completed On:

June 25, 2001

Comments:

Confirmed Pirate Device (decoder)

FOR OFFICE USE ONLY:

CONVERTER INSTALLED

BY

CONVERTER REMOVED

3/9/01

BY

TAUNTON POLICE DEPARTMENT

ACCOUNT HISTORY SUMMARY

EVIDENCE # 3C PACKAGE # 3

AT&T BROADBAND
CONVERTER TEST FORM

Date	3-9-01	Corp. #	I-COMS
Account #	43747-04	Converter #	010200363
Name:	Joe Amaro / Dimas Amaro	Converter Type:	View Master 4040
Address:	333 Cohannet Street	Received From:	UPS pursuant to warrant on 3/9/01
City:	Taunton	State/Zip	Ma. 02780
SSN#:		Generated From:	

Currently Receiving Unauthorized Service:

All Pay Channels	<u>Yes</u>	All PPV Movies	<u>Yes</u>
Pre 4 Point Test			

CODES RECEIVED

OTHER NOTABLE FEATURES

OUTSIDE CONVERTER APPEARANCE

<u>P</u>	Security Tabs Missing
<u>I</u>	Outside Screws Missing
<u>R</u>	Converter Damaged
<u>A</u>	Marks Around Outside Screw
<u>T</u>	Wires Cut
<u>E</u>	Tampered Codes

INSIDE CONVERTER APPEARANCE

<u>U</u>	ADP Module Forced Open
<u>N</u>	ADP Module Cover Missing
<u>I</u>	Scratches/Marks on Key Chips
<u>I</u>	Jumper Wires Still In Place
<u>T</u>	Scratches/Marks on Legs of Key Chips
	Missing Prom #

4 Point Test

	Testing Point	Codes/Comments	Pass/Fail
1.	Check Video on converter (e.g. channel 5 or PPV barker on all channels.)	<u>P</u>	<u>U</u>
2.	Converter has 210 code or higher	<u>I</u>	<u>N</u>
3.	Converter has H-1 or H6 code, or tunes 01-99 or 01-128 consecutively.	<u>R</u>	<u>I</u>
4.	Converter does not initialize (i.e. an addressable hit)	<u>ATE</u>	<u>T</u>

Of the 4 points, how many points does it have?

Test Completed By:

Special Project Auditor Paul Marmelo

Date Completed On:

June 25, 2001

Comments:

Confirmed Pirate Device (decoder)

FOR OFFICE USE ONLY:

CONVERTER INSTALLED

BY

CONVERTER REMOVED

3/9/01

BY

TAUNTON POLICE DEPARTMENT

ACCOUNT HISTORY SUMMARY

EVIDENCE # 3D PACKAGE # 3

AT&T BROADBAND
CONVERTER TEST FORM

Date	3-9-01	Corp. #	I-COMS
Account #	43747-04	Converter #	010200570
Name:	Joe Amaro / Dimas Amaro	Converter Type:	View Master 4040
Address:	333 Cohannet Street	Received From:	UPS pursuant to warrant on 3/9/01
City:	Taunton	State/Zip	Ma. 02780
SSN#:		Generated From:	

Currently Receiving Unauthorized Service:

All Pay Channels	<u>Yes</u>	All PPV Movies	<u>Yes</u>
Pre 4 Point Test			

CODES RECEIVED

OTHER NOTABLE FEATURES

OUTSIDE CONVERTER APPEARANCE

<u>P</u>	Security Tabs Missing
<u>I</u>	Outside Screws Missing
<u>R</u>	Converter Damaged
<u>A</u>	Marks Around Outside Screw
<u>T</u>	Wires Cut
<u>E</u>	Tampered Codes

INSIDE CONVERTER APPEARANCE

<u>U</u>	ADP Module Forced Open
<u>N</u>	ADP Module Cover Missing
<u>I</u>	Scratches/Marks on Key Chips
<u>T</u>	Jumper Wires Still In Place
<u>T</u>	Scratches/Marks on Legs of Key Chips
	Missing Prom #

4 Point Test

	Testing Point	Codes/Comments	Pass/Fail
1.	Check Video on converter (e.g. channel 5 or PPV barker on all channels.)	<u>P</u>	<u>U</u>
2.	Converter has 210 code or higher	<u>I</u>	<u>N</u>
3.	Converter has H-1 or H6 code, or tunes 01-99 or 01-128 consecutively.	<u>R</u>	<u>I</u>
4.	Converter does not initialize (i.e. an addressable hit)	<u>ATE</u>	<u>T</u>

Of the 4 points, how many points does it have?

Test Completed By:

Special Project Auditor Paul Marmelo

Date Completed On:

June 25, 2001

Comments:

Confirmed Pirate Device (decoder)

FOR OFFICE USE ONLY:

CONVERTER INSTALLED

BY

CONVERTER REMOVED

3/9/01

BY

TAUNTON POLICE DEPARTMENT

ACCOUNT HISTORY SUMMARY

EVIDENCE # 3E PACKAGE # 3

AT&T BROADBAND
CONVERTER TEST FORM

Date	3-9-01	Corp. #	I-COMS
Account #	43747-04	Converter #	010200084
Name:	Joe Amaro / Dimas Amaro	Converter Type:	View Master 4040
Address:	333 Cohannet Street	Received From:	UPS pursuant to warrant on 3/9/01
City:	Taunton	State/Zip	Ma. 02780
SSN#:		Generated From:	

Currently Receiving Unauthorized Service:

All Pay Channels	<u>Yes</u>	All PPV Movies	<u>Yes</u>
Pre 4 Point Test			

CODES RECEIVED

OTHER NOTABLE FEATURES

OUTSIDE CONVERTER APPEARANCE

<u>P</u>	Security Tabs Missing
<u>I</u>	Outside Screws Missing
<u>R</u>	Converter Damaged
<u>A</u>	Marks Around Outside Screw
<u>T</u>	Wires Cut
<u>E</u>	Tampered Codes

INSIDE CONVERTER APPEARANCE

<u>U</u>	ADP Module Forced Open
<u>N</u>	ADP Module Cover Missing
<u>I</u>	Scratches/Marks on Key Chips
<u>T</u>	Jumper Wires Still In Place
<u>T</u>	Scratches/Marks on Legs of Key Chips
	Missing Prom #

4 Point Test

	Testing Point	Codes/Comments	Pass/Fail
1.	Check Video on converter (e.g. channel 5 or PPV barker on all channels.)	<u>P</u>	<u>U</u>
2.	Converter has 210 code or higher	<u>I</u>	<u>N</u>
3.	Converter has H-1 or H6 code, or tunes 01-99 or 01-128 consecutively.	<u>R</u>	<u>I</u>
4.	Converter does not initialize (i.e. an addressable hit)	<u>ATE</u>	<u>T</u>

Of the 4 points, how many points does it have?

Test Completed By:

Special Project Auditor Paul Marmelo

Date Completed On:

June 25, 2001

Comments:

Confirmed Pirate Device (decoder)

FOR OFFICE USE ONLY:

CONVERTER INSTALLED

BY

CONVERTER REMOVED

3/9/01

BY

TAUNTON POLICE DEPARTMENT

ACCOUNT HISTORY SUMMARY

EVIDENCE # 3F PACKAGE # 3

AT&T BROADBAND
CONVERTER TEST FORM

Date	3-9-01	Corp. #	I-COMS
Account #	43747-04	Converter #	010201511
Name:	Joe Amaro / Dimas Amaro	Converter Type:	View Master 4040
Address:	333 Cohannet Street	Received From:	UPS - pursuant to warrant on 3/9/01
City:	Taunton	State/Zip	Ma. 02780
SSN#:		Generated From:	

Currently Receiving Unauthorized Service:

All Pay Channels	<u>Yes</u>	All PPV Movies	<u>Yes</u>
Pre 4 Point Test			

CODES RECEIVED

OTHER NOTABLE FEATURES

OUTSIDE CONVERTER APPEARANCE

<u>P</u>	Security Tabs Missing
<u>I</u>	Outside Screws Missing
<u>R</u>	Converter Damaged
<u>A</u>	Marks Around Outside Screw
<u>T</u>	Wires Cut
<u>E</u>	Tampered Codes

INSIDE CONVERTER APPEARANCE

<u>U</u>	ADP Module Forced Open
<u>N</u>	ADP Module Cover Missing
<u>I</u>	Scratches/Marks on Key Chips
<u>T</u>	Jumper Wires Still In Place
<u>T</u>	Scratches/Marks on Legs of Key Chips
	Missing Prom #

4 Point Test

	Testing Point	Codes/Comments	Pass/Fail
1.	Check Video on converter (e.g. channel 5 or PPV barker on all channels.)	<u>P</u>	<u>U</u>
2.	Converter has 210 code or higher	<u>I</u>	<u>N</u>
3.	Converter has H-1 or H6 code, or tunes 01-99 or 01-128 consecutively.	<u>R</u>	<u>I</u>
4.	Converter does not initialize (i.e. an addressable hit)	<u>ATE</u>	<u>T</u>

Of the 4 points, how many points does it have?

Test Completed By:

Special Project Auditor Paul Marmelo

Date Completed On:

June 25, 2001

Comments:

Confirmed Pirate Device (decoder)

FOR OFFICE USE ONLY:

CONVERTER INSTALLED

BY

CONVERTER REMOVED

3/9/01

BY

TAUNTON POLICE DEPARTMENT

ACCOUNT HISTORY SUMMARY

EVIDENCE # 3G PACKAGE # 3

AT&T BROADBAND
CONVERTER TEST FORM

Date	3-9-01	Corp. #	<u>I-COMS</u>
Account #	43747-04	Converter #	010200364
Name:	Joe Amaro / Dimas Amaro	Converter Type:	<u>View Master 4040</u>
Address:	333 Cohannet Street	Received From:	<u>UPS pursuant to warrant on</u> <u>3/9/01</u>
City:	Taunton	State/Zip	<u>Ma. 02780</u>
SSN#:		Generated From:	

Currently Receiving Unauthorized Service:

All Pay Channels	<u>Yes</u>	All PPV Movies	<u>Yes</u>
------------------	------------	----------------	------------

Pre 4 Point Test

CODES RECEIVED

OTHER NOTABLE FEATURES

OUTSIDE CONVERTER APPEARANCE

<u>P</u>	Security Tabs Missing
<u>I</u>	Outside Screws Missing
<u>R</u>	Converter Damaged
<u>A</u>	Marks Around Outside Screw
<u>T</u>	Wires Cut
<u>E</u>	Tampered Codes

INSIDE CONVERTER APPEARANCE

<u>U</u>	ADP Module Forced Open
<u>N</u>	ADP Module Cover Missing
<u>I</u>	Scratches/Marks on Key Chips
<u>I</u>	Jumper Wires Still In Place
<u>T</u>	Scratches/Marks on Legs of Key Chips
	Missing Prom #

4 Point Test

	Testing Point	Codes/Comments	Pass/Fail
1.	Check Video on converter (e.g. channel 5 or PPV barker on all channels.)	<u>P</u>	<u>U</u>
2.	Converter has 210 code or higher	<u>I</u>	<u>N</u>
3.	Converter has H-1 or H6 code, or tunes 01-99 or 01-128 consecutively.	<u>R</u>	<u>I</u>
4.	Converter does not initialize (i.e. an addressable hit)	<u>ATE</u>	<u>T</u>

Of the 4 points, how many points does it have?

Test Completed By:

Special Project Auditor Paul Marmelo

Date Completed On:

June 25, 2001

Comments:

Confirmed Pirate Device (decoder)

FOR OFFICE USE ONLY:

CONVERTER INSTALLED

BY

CONVERTER REMOVED

3/9/01

BY

TAUNTON POLICE DEPARTMENT

ACCOUNT HISTORY SUMMARY

EVIDENCE # 3H PACKAGE #3

AT&T BROADBAND
CONVERTER TEST FORM

Date 3-9-01 Corp. # I-COMS
 Account # 43747-04 Converter # 010200124
 Name: Joe Amaro / Dimas Amaro Converter Type: View Master 4040
 Address: 333 Cohannet Street Received From: UPS pursuant to warrant on
3/9/01.
 City: Taunton State/Zip Ma. 02780
 SSN#: _____ Generated From: _____

Currently Receiving Unauthorized Service:

All Pay Channels Yes All PPV Movies Yes
 Pre 4 Point Test

CODES RECEIVED

OTHER NOTABLE FEATURES

OUTSIDE CONVERTER APPEARANCE

P Security Tabs Missing
I Outside Screws Missing
R Converter Damaged
A Marks Around Outside Screw
T Wires Cut
E Tampered Codes

INSIDE CONVERTER APPEARANCE

U ADP Module Forced Open
U ADP Module Cover Missing
N Scratches/Marks on Key Chips
I Jumper Wires Still In Place
T Scratches/Marks on Legs of Key Chips
 Missing Prom #

4 Point Test

Testing Point	Codes/Comments	Pass/Fail
1. Check Video on converter (e.g. channel 5 or PPV barker on all channels.)	<u>P</u>	<u>U</u>
2. Converter has 210 code or higher	<u>I</u>	<u>N</u>
3. Converter has H-1 or H6 code, or tunes 01-99 or 01-128 consecutively.	<u>R</u>	<u>I</u>
4. Converter does not initialize (i.e. an addressable hit)	<u>ATE</u>	<u>T</u>

Of the 4 points, how many points does it have?

Test Completed By:

Special Project Auditor Paul Marmelo

Date Completed On:

June 25, 2001

Comments:

Confirmed Pirate Device (decoder)

FOR OFFICE USE ONLY:

CONVERTER INSTALLED

BY

CONVERTER REMOVED

3/9/01

BY

TAUNTON POLICE DEPARTMENT

ACCOUNT HISTORY SUMMARY

AT&T BROADBAND
CONVERTER TEST FORM

EVIDENCE # 3I PACKAGE #3

Date 3-9-01 Corp. # I-COMS
 Account # 43747-04 Converter # 010200137
 Name: Joe Amaro / Dimas Amaro Converter Type: View Master 4040
 Address: 333 Cohannet Street Received From: UPS pursuant to warrant on
3/9/01
 City: Taunton State/Zip Ma. 02780
 SSN#: _____ Generated From: _____

Currently Receiving Unauthorized Service:

All Pay Channels Yes All PPV Movies Yes
 Pre 4 Point Test

CODES RECEIVED

OTHER NOTABLE FEATURES

OUTSIDE CONVERTER APPEARANCE

P Security Tabs Missing
I Outside Screws Missing
R Converter Damaged
A Marks Around Outside Screw
T Wires Cut
E Tampered Codes

INSIDE CONVERTER APPEARANCE

U ADP Module Forced Open
N ADP Module Cover Missing
I Scratches/Marks on Key Chips
T Jumper Wires Still In Place
T Scratches/Marks on Legs of Key Chips
 Missing Prom # _____

4 Point Test

Testing Point	Codes/Comments	Pass/Fail
1. Check Video on converter (e.g. channel 5 or PPV barker on all channels.)	<u>P</u>	<u>U</u>
2. Converter has 210 code or higher	<u>I</u>	<u>N</u>
3. Converter has H-1 or H6 code, or tunes 01-99 or 01-128 consecutively.	<u>R</u>	<u>I</u>
4. Converter does not initialize (i.e. an addressable hit)	<u>ATE</u>	<u>T</u>

Of the 4 points, how many points does it have?

Test Completed By:

Special Project Auditor Paul Marmelo

Date Completed On:

June 25, 2001

Comments:

Confirmed Pirate Device (decoder)

FOR OFFICE USE ONLY:

CONVERTER INSTALLED

BY

CONVERTER REMOVED

3/9/01

BY

TAUNTON POLICE DEPARTMENT

ACCOUNT HISTORY SUMMARY

EVIDENCE # 3J PACKAGE # 3

AT&T BROADBAND
CONVERTER TEST FORM

Date 3-9-01 Corp. # I-COMS
 Account # 43747-04 Converter # 010200368
 Name: Joe Amaro / Dimas Amaro Converter Type: View Master 4040
 Address: 333 Cohannet Street Received From: UPS pursuant to warrant on
3/9/01
 City: Taunton State/Zip Ma. 02780
 SSN#: _____ Generated From: _____

Currently Receiving Unauthorized Service:

All Pay Channels Yes All PPV Movies Yes

Pre 4 Point Test

CODES RECEIVED

OTHER NOTABLE FEATURES

OUTSIDE CONVERTER APPEARANCE

P Security Tabs Missing
I Outside Screws Missing
R Converter Damaged
A Marks Around Outside Screw
T Wires Cut
E Tampered Codes

INSIDE CONVERTER APPEARANCE

U ADP Module Forced Open
U ADP Module Cover Missing
N Scratches/Marks on Key Chips
I Jumper Wires Still In Place
T Scratches/Marks on Legs of Key Chips
 _____ Missing Prom #

4 Point Test

Testing Point	Codes/Comments	Pass/Fail
1. Check Video on converter (e.g. channel 5 or PPV barker on all channels.)	<u>P</u>	<u>U</u>
2. Converter has 210 code or higher	<u>I</u>	<u>N</u>
3. Converter has H-1 or H6 code, or tunes 01-99 or 01-128 consecutively.	<u>R</u>	<u>I</u>
4. Converter does not initialize (i.e. an addressable hit)	<u>ATE</u>	<u>T</u>

Of the 4 points, how many points does it have?

Test Completed By:

Special Project Auditor Paul Marmelo

Date Completed On:

June 25, 2001

Comments:

Confirmed Pirate Device (decoder)

FOR OFFICE USE ONLY:

CONVERTER INSTALLED

BY

CONVERTER REMOVED

3/9/01

BY

TAUNTON POLICE DEPARTMENT

ACCOUNT HISTORY SUMMARY

EVIDENCE # 3K PACKAGE # 3

AT&T BROADBAND
CONVERTER TEST FORM

Date	3-9-01	Corp. #	I-COMS
Account #	43747-04	Converter #	010200073
Name:	Joe Amaro / Dimas Amaro	Converter Type:	View Master 4040
Address:	333 Cohannet Street	Received From:	UPS pursuant to warrant on 3/9/01
City:	Taunton	State/Zip	Ma. 02780
SSN#:		Generated From:	

Currently Receiving Unauthorized Service:

All Pay Channels Yes All PPV Movies Yes

Pre 4 Point Test

CODES RECEIVED

OTHER NOTABLE FEATURES

OUTSIDE CONVERTER APPEARANCE

<u>P</u>	Security Tabs Missing
<u>I</u>	Outside Screws Missing
<u>R</u>	Converter Damaged
<u>A</u>	Marks Around Outside Screw
<u>T</u>	Wires Cut
<u>E</u>	Tampered Codes

INSIDE CONVERTER APPEARANCE

<u>U</u>	ADP Module Forced Open
<u>N</u>	ADP Module Cover Missing
<u>I</u>	Scratches/Marks on Key Chips
<u>T</u>	Jumper Wires Still In Place
<u>T</u>	Scratches/Marks on Legs of Key Chips
	Missing Prom #

4 Point Test

	Testing Point	Codes/Comments	Pass/Fail
1.	Check Video on converter (e.g. channel 5 or PPV barker on all channels.)	<u>P</u>	<u>U</u> N/A
2.	Converter has 210 code or higher	<u>I</u>	<u>N</u> N/A
3.	Converter has H-1 or H6 code, or tunes 01-99 or 01-128 consecutively.	<u>R</u>	<u>I</u> N/A
4.	Converter does not initialize (i.e. an addressable hit)	<u>ATE</u>	<u>T</u> N/A

Of the 4 points, how many points does it have?

N/A

Test Completed By:

Special Project Auditor Paul Marmelo

Date Completed On:

June 25, 2001

Comments:

Confirmed Pirate Device (decoder)

FOR OFFICE USE ONLY:

CONVERTER INSTALLED

BY

CONVERTER REMOVED

3/9/01

BY

TAUNTON POLICE DEPARTMENT

ACCOUNT HISTORY SUMMARY

EVIDENCE # 3L PACKAGE #3

AT&T BROADBAND
CONVERTER TEST FORM

Date	3-9-01	Corp. #	I-COMS
Account #	43747-04	Converter #	010201198
Name:	Joe Amaro / Dimas Amaro	Converter Type:	View Master Platinum Plus
Address:	333 Cohannet Street	Received From:	UPS pursuant to warrant on 3/9/01
City:	Taunton	State/Zip	Ma. 02780
SSN#:		Generated From:	

Currently Receiving Unauthorized Service:

All Pay Channels	<u>Yes</u>	All PPV Movies	<u>Yes</u>
Pre 4 Point Test			

CODES RECEIVED

OTHER NOTABLE FEATURES

OUTSIDE CONVERTER APPEARANCE

<u>P</u>	Security Tabs Missing
<u>I</u>	Outside Screws Missing
<u>R</u>	Converter Damaged
<u>A</u>	Marks Around Outside Screw
<u>T</u>	Wires Cut
<u>E</u>	Tampered Codes

INSIDE CONVERTER APPEARANCE

<u>U</u>	ADP Module Forced Open
<u>N</u>	ADP Module Cover Missing
<u>I</u>	Scratches/Marks on Key Chips
<u>T</u>	Jumper Wires Still In Place
<u>T</u>	Scratches/Marks on Legs of Key Chips
	Missing Prom #

4 Point Test

	Testing Point	Codes/Comments	Pass/Fail
1.	Check Video on converter (e.g. channel 5 or PPV barker on all channels.)	<u>P</u>	<u>U</u> N/A
2.	Converter has 210 code or higher	<u>I</u>	<u>N</u> N/A
3.	Converter has H-1 or H6 code, or tunes 01-99 or 01-128 consecutively.	<u>R</u>	<u>I</u> N/A
4.	Converter does not initialize (i.e. an addressable hit)	<u>ATE</u>	<u>T</u> N/A

Of the 4 points, how many points does it have?

N/A

Test Completed By:

Special Project Auditor Paul Marmelo

Date Completed On:

June 25, 2001

Comments:

Confirmed Pirate Device (decoder)

FOR OFFICE USE ONLY:

CONVERTER INSTALLED

BY

CONVERTER REMOVED

3/9/01

BY

TAUNTON POLICE DEPARTMENT

ACCOUNT HISTORY SUMMARY